

CAT 3612

Stock No: 350524 Make: AA Model: 3612 Serial No: 09RC00017 Division: P FPC: I
 Eq Sts: U Inv Sts: S Last SMU: 20663 H SMU Date: 08-May-09
 Eng Make: Eng Model: Eng S/N: Eng Arr No: Trans Make: Trans S/N:

Total Work Orders: 21 Total Parts: 324,280.15
 Total Amount: 877,303.53 Total Labour: 529,711.11
 Total Lbr Hours: 3337.75 Total Misc: 23,312.27
 Total Flat Rate Amount: 0.00

Last 4 Years of Work Order History displayed below.
 If searching detail older than 4 years, please refer to DBS. DSPEMEMR EQUIPMENT MAINTENANCE & REPAIR REVIEW (INVOICED).

Cust: Job: Comp:
 Code:

Customer	Open Date	Hours	Work Order	A/I	Job	Comp	Pt	Cust	Lbr Cust	Misc Cust	Seg Total	Notes
4704301	19-Aug-10	0	<u>0806023</u> - 01	C	056	1000					3,719.57	TRAVEL
			<u>0806023</u> - 02	C	048	1000					2,181.00	PRELIMINARY START AFTER STORAGE
											WO Total: 5,900.57	
4704301	08-May-09	20663	<u>0805128</u> - 01	C	056	1000					2,455.00	TRAVEL
			<u>0805128</u> - 02	C	040	1000					3,045.00	INSPECT PISTON AND LINERS
											WO Total: 5,500.00	
4704301	06-Apr-09	20043	<u>0805080</u> - 01	C	056	1000					3,049.17	TRAVEL EXPENSES
			<u>0805080</u> - 02	C	023	9407					37,929.91	REPAIR #9 CYLINDER
			<u>0805080</u> - 03	C	269	1052					2,371.25	ASSIST WITH RH TURBO INSTALL

CAT 3612

WO Total: 43,350.33

4704301 26-Feb-09 20053 0805026 - 02 C 023 1000

68,561.13 CHECK AND REPAIR UNIT
FOR COOLANT IN THE BASE.

WO Total: 68,561.13

4704301 18-Feb-09 20053 0805017 - 01 C 056 1000

4,866.69 TRAVEL EXPENSES

0805017 - 02 C 010 1052

10,168.00 RE&RE TURBOS TO SEND
OUT FOR OVERHAUL USING
YECL

TURBO UNTIL OVERHAUL
COMPLETE

0805017 - 03 C 040 1052

1,390.50 PICK UP TURBO FROM YECL
AND INSPECT CONDITION OF

TURBO FOR USEABILITY

INSPECT AND CRATE YECL
TURBO TO RETURN TO YECL

WO Total: 16,425.19

4704301 19-Jan-09 9444 0804975 - 01 C 056 1000

4,725.02 TRAVEL TO/FROM ENGINE

0804975 - 02 C 011 1063

12,654.47 REMOVE AFTER COOLERS
TO CLEANED & TESTED @
YUKON R

AD.

0804975 - 03 C 540 9700

15,874.17 PERFORM PERFORMANCE
ANALYSIS ON TURBO
CHARGERS

WO Total: 33,253.66

4704301 09-Dec-08 0 0804922 - 01 C 056 1000 656.61 TRAVEL EXPENSES
[REDACTED]
0804922 - 02 C 540 9700 6,752.69 PERFORMANCE ANALYSIS
IN REGARDS TO ENGINE
LOSING
POWER
WO Total: 7,409.30

4704300 29-Sep-08 0 0804816 - 01 C 056 1000 3,454.82 TRAVEL AND
ACCOMODATION
[REDACTED]
0804816 - 02 C 035 1000 3,853.14 CHECK AND REAPIR ENGINE
FOR HEAVY BLACK SMOKE
WO Total: 7,307.96

4704301 23-Sep-08 6986 0804795 - 01 C 056 1000 4,380.50 TRAVEL AND
ACCOMODATION
[REDACTED]
0804795 - 02 C 012 1160 3,067.75 INSTALL UPDATED FRONT
CRANKSHAFT SEAL
[REDACTED]
0804795 - 03 C 900 1160 4,602.26 ADDITONALS
WO Total: 12,050.51

4704301 18-Jun-08 15023 0804653 - 01 C 056 1000 3,735.62 TRAVEL TIME TO & FROM
THE MINE SITE.
[REDACTED]
0804653 - 02 C 023 1160 6,695.92 REPLACE FRONT
CRANKSHAFT SEAL.
[REDACTED]
0804653 - 03 C 023 1000 2,362.75 MISCELLANEOUS REPAIRS.
WO Total: 12,794.29

4704300 14-Apr-08 7155 0804573 - 01 C 056 1000 3,178.88 FOR TRAVEL BETWEEN
WATSON LAKE AND MINE
SITE

0804573 - 02 C 035 1000 6,544.26 CHECK ENGINE FOR
INJECTOR FAILURE

WO Total: 9,723.14

4704300 20-Feb-08 0 0804500 - 51 C 269 1290 WPWTP08 WPWTP08 WPWTP08 1,137.41 REPLACE FAILED FOR
WARRANTY

WO Total: 1,137.41

4704300 11-Feb-08 2377 0804491 - 01 C 056 1000 4,356.49 TRAVEL AND
ACCOMODATION

0804491 - 02 C 023 1102 16,450.00 REPAIR FOR BROKEN
ROCKER GEAR

0804491 - 03 C 900 1000 272.63 ADDITIONALS RELATED TO
ENGINE REPAIR

0804491 - 04 C 025 9117 (625.00)

WO Total: 20,454.12

4704300 27-Dec-07 0 0804441 - 02 C 999 9080 PCOSR08 PCOSR08 PCOSR08 945.27 CORE CHARGE TO BR 08
PARTS POLICY

WO Total: 945.27

4704300 19-Sep-07 9986 0804313 - 01 C 056 1000 673.00 TRAVEL TO/FROM MACHINE

0804313 - 02 C 011 6000 1,686.76 REMOVE DATA LOGGER

WO Total: 2,359.76

h.OpenDate desc	desc
-----------------	------

Make: AA Ser No: 09RC00017 Model: 3612 Div: P Prod Code: I
 Eqp Sts: U Inv Sts: S Warr types:
 Last Known SMU: 20,663.0 H (H,M,K) Acquis Dt: 5/10/05 Labor Hours: 5,764
 Parts: 324,280.15 Labor: 529,711.11 Misc: 23,312.27
 Total Parts, Labor, Miscellaneous and Flat Rate All: 877,303.53

SEGMENT DETAIL

Invoice Dt 4/06/09 Repairs REPAIR ENGINE
 Invc/Doc 0805026 Seg 02 Dt Open 2/26/09 In-Proc Days 40 Lst SMU 20053.0
 Labor Hours 153.00 Customer 4704301 NORTH AMERICAN TUNGSTEN PIP No
 Pts 36238.16 Labr 29775.50 Msc 2547.47 Totl 68561.13
 Warr Reference Type Code Claim No Claim Ind N

Invoice Dt 2/19/09 Repairs TRAVEL TO/FROM ENGINE
 Invc/Doc 0804975 Seg 01 Dt Open 1/19/09 In-Proc Days 32 Lst SMU 9444.0
 Labor Hours 25.00 Customer 4704301 NORTH AMERICAN TUNGSTEN PIP No
 Pts .00 Labr 4543.75 Msc 181.27 Totl 4725.02
 Warr Reference Type Code Claim No Claim Ind N

+

CF3:Fold

Make: AA Ser No: 09RC00017 Model: 3612 Div: P Prod Code: I
 Eqp Sts: U Inv Sts: S Warr types:
 Last Known SMU: 20,663.0 H (H,M,K) Acquis Dt: 5/10/05 Labor Hours: 5,764
 Parts: 324,280.15 Labor: 529,711.11 Misc: 23,312.27
 Total Parts, Labor, Miscellaneous and Flat Rate All: 877,303.53

SEGMENT DETAIL

Invoice Dt 5/20/09 Repairs TRAVEL TO/FROM ENGINE
 Invc/Doc 0805128 Seg 01 Dt Open 5/08/09 In-Proc Days 13 Lst SMU 20663.0
 Labor Hours 20.00 Customer 4704301 NORTH AMERICAN TUNGSTEN PIP No
 Pts .00 Labr 2455.00 Msc .00 Totl 2455.00
 Warr Reference Type Code Claim No Claim Ind N

Invoice Dt 5/20/09 Repairs INSPECT ENGINE
 Invc/Doc 0805128 Seg 02 Dt Open 5/08/09 In-Proc Days 13 Lst SMU 20663.0
 Labor Hours 20.00 Customer 4704301 NORTH AMERICAN TUNGSTEN PIP No
 Pts .00 Labr 3045.00 Msc .00 Totl 3045.00
 Warr Reference Type Code Claim No Claim Ind N

+

CF3:Fold