



14519 East Freeway
Houston Texas, 77024
936-443-4378

LOAD TEST REPORT

Account Name: _____
 Equipment Location: (Physical Address) Shop
 Work Order Number: _____
 Engine MT4 Generator Kohler
506R0204
0663373
 PASS / FAIL

Engine Fluids:
 Oil Level F411
 Coolant Level F411
 Beg. Fuel Level 40%
 End Fuel Level _____

Service Technician Paul Rubin Test Date 3-7-22
 Customer Witness _____

Test Equipment
 Make: _____
 Model: 57mP/ep
 Serial Number: cececece

Line	Time	Hour Meter	Volt Meter	Frequency (Hz)	Power (KW)	Leg A Amps	Leg B Amps	Leg C Amps	Oil Pressure (PSI)	Water Temp (F)	Ambient Temp (F)
1	12:54	1003.3	480	60	0	0	0	0	100	140	55
2	12:55	1003.3	480	60	150kw	194	194	194	85	120	55
3	1:10	1003.6	480	60	150kw	194	196	194	65	170	55
4	1:25	1003.9	480	60	150kw	194	196	176	65	170	55
5	1:25	1003.9	480	60	250kw	300	301	302	60	175	55
6	1:40	1004.1	480	60	250kw	306	305	306	50	175	55
7	1:55	1004.3	480	60	250kw	306	305	306	50	175	55
8	1:55	1004.3	480	60	400kw	506	506	504	50	175	55
9	2:10	1004.6	480	60	400kw	506	506	506	50	175	55
10	2:25	1004.9	480	60	400kw	506	504	506	50	175	55
11	2:40	1005.1	480	60	400kw	506	504	504	50	175	59
12	2:55	1005.3	480	60	400kw	506	504	504	50	179	55
13	2:55	1005.3	480	60	0	0	0	0	50	170	55