



GenSolutions LLC

11729 Spriggs Way  
Houston Texas, 77024  
936-443-4378

# LOAD TEST REPORT

Account Name:

Power Gen Enterprises

Equipment Location: (Physical Address)

IN SHOP

Work Order Number:

Engine

Generator

John Deere

MQ

4068

DC422055JU

PE60685075L3P

8010278

PASS/FAIL

Engine Fluids:

Oil Level	Full
Coolant Level	Full
Beg. Fuel Level	—
End Fuel Level	—

Service Technician

Phil Bolin

Test Date

Customer Witness

Test Equipment

Simplex

200Kw

Make:  
Model:  
Serial Number:

Line	Time	Hour Meter	Volt Meter	Frequency (Hz)	Power (KW)	Leg A Amps	Leg B Amps	Leg C Amps	Oil Pressure (PSI)	Water Temp (F)	Ambient Temp (F)
	9:45	1106.9	480	60	60	72	72	72	55	175	77
	8:00	11109.2	480	60	60	72	72	72	55	175	77
	8:15	11107.4	480	60	60	72	72	72	55	175	77
	8:30	11107.7	480	60	110	132	132	132	55	180	78
	8:45	11107.9	480	60	110	133	132	133	55	180	78
	9:00	11108.2	480	60	110	132	132	133	55	180	78
	9:15	11108.4	480	60	180	217	217	217	55	185	78
	9:30	11108.7	480	60	180	217	217	217	50	195	78
	9:45	11108.9	480	60	180	217	217	217	50	195	78
	9:50	11109.0	480	60	180	217	217	217	50	180	78